

US EPA ARCHIVE DOCUMENT

UNIT LOG		1. Incident Name Kalamazoo River/Enbridge Oil Spill	2. Date Prepared 09/25/2012	3. Time Prepared 1645
4. Unit Name/Designators Situation Unit		5. Unit Leader (Name and Position) Melinda Luetke, Planning Section Chief		6. Operational Period 0700, 09/20/12 – 0700, 09/27/12
7. Personnel Roster Assigned				
Name		ICS Position		Home Base
Larry Rader		Situation Unit Leader		Chicago, Illinois
8. Activity Log				
Time	Major Events			
0900	<p>Boat safety briefing at C0.4 boat launch. Launch.</p> <p>Operational status:</p> <ul style="list-style-type: none"> · Observed sheen and tar globules along MP 5.75 LDB near trestle. · Observed sheen and tar globules within containment at control point above Ceresco Dam. · Observed crews removing vegetation and debris from containment boom above Ceresco Dam. · Observed sheen and tar globules at MP 15.50 (north end of south Mill Pond) RDB following agitation if sediment by boat. · Observed sediment trap at MP 36.1 RDB, no sheen observed. Some debris observed behind sediment trap structure. · Observed poling and bathymetry crews operating along northern and southern shorelines of Morrow Lake Delta. · Observed boom and curtain inspection crew working along boom configuration E in Morrow Lake Delta. · Observed sheen sweeper boat operating in southern cove of Morrow Lake. Sheen and tar globules were observed in the southern cove. · Observed sheen in northern cove of Morrow Lake following agitation by boat. 			
	Additional observations: None			
1520	Return to ICP.			
9. Prepared by (Name and Position) Larry Rader, Situation Unit Leader, USEPA-START				