

US EPA ARCHIVE DOCUMENT

<b>1. Incident Name</b>	<b>2. Date Prepared</b>	<b>3. Time Prepared</b>	<b>UNIT LOG ICS 214</b>	
Kalamazoo River/Enbridge Spill	10/1/2012	1750		
<b>4. Unit Name/Designators</b>	<b>5. Unit Leader</b>		<b>6. Operational Period :</b>	
Containment Branch Recovery Team 1	<b>Name:</b>	Dan Capone & Joe Victory (START/US EPA)	<b>From:</b>	10/1/2012 0700
	<b>Position:</b>	Operations Section Chief	<b>To:</b>	10/1/2012 1750
<b>7. Personnel Roster Assigned</b>				
<u>Name</u>		<u>ICS Position</u>	<u>DUTY CELL</u>	
Dan Capone		Operations Section Chief		
Chris Lantinga		Operations Section Chief		
Rex Johnson		Containment Branch Director		
Dan Zahner		Field Team Lead		
Marc Wahrer		CBR-1		
<b>8. Activity Log</b>				
<b>Activity Area</b>	E4 boom video oversight – D, ES and EN boom		<b>LAT</b>	<b>LAT</b>
			<b>Various</b>	<b>Various</b>
			(DD.MMMM)	(DD.MMMM)
<b><u>OIL OBSERVED</u></b>	<b>EXTENT OF OIL IMPACTED AREA</b>			
	<b>DENSITY OF OIL /SHEEN</b>			
<b>Total Collection Points</b>				
<b>Total Boom Deployed</b>				
<b>Activity</b>	<b><u>Weston/START CBR 2 Team Activity:</u></b>			
	<ul style="list-style-type: none"> <li>Oversaw Enbridge Field Team including Clark, Travis and Mike for video monitoring of E4 boom at the delta area. They collected video of the curtain and depths at approximately 25 foot increments along the boom (water depth, height of curtain, and whether there was any visible openings in the curtain at the bottom by the sediment). They made adjustments to the curtain height (up or down) if necessary. They made two adjustments today, ES200 – moved curtain down, and EN625 – fixed broken strap that let curtain fall down slightly in this area.</li> </ul>			
<b>Health and Safety Issues</b>				
<b>Comments</b>	Field notes are in CBR-1 Logbook			