

US EPA ARCHIVE DOCUMENT

UNIT LOG		1. Incident Name Kalamazoo River/Enbridge Oil Spill	2. Date Prepared 10/01/2012	3. Time Prepared 1700
4. Unit Name/Designators Situation Unit		5. Unit Leader (Name and Position) Melinda Leutke, Planning Section Chief		6. Operational Period 0700, 09/27/2012 – 0700, 10/04/2012
7. Personnel Roster Assigned				
Name		ICS Position		Home Base
Larry Rader		Situation Unit Leader		Chicago, Illinois
8. Activity Log				
Time	Major Events			
0800	<ul style="list-style-type: none"> • MP 5.63 RDB, no sheen observed along shoreline upstream of trestle. • Crews observed removing debris from Ceresco Dam control point. • Sheen and tar globules observed within containment along Ceresco Dam control point. • Sheen observed along LDB at Ceresco Dam near upstream portage. • RI crews observed collecting samples along LDB near MP 8.0. • MP 15.5 South Mill Pond RDB of river channel, no sheen observed. • View of culverts at MP 15.75 in North Mill Pond. No sheen observed. • Poling crew observed operating along boom B in Morrow Lake Delta. • Sheen and tar globules observed along boom C in Morrow Lake Delta. • Curtain inspection crew observed working along boom E2. • Crews observed removing debris from E2 control point boom in Morrow Lake Delta. • North cove of Morrow Lake. No sheen observed. • South cove of Morrow Lake, no sheen or tar globules observed. • Main river channel of Morrow Lake, no sheen or tar globules observed. 			
1500	Finish up inspections at E4.0 boat launch.			
9. Prepared by (Name and Position) Larry Rader, Situation Unit Leader, USEPA-START				