

US EPA ARCHIVE DOCUMENT

UNIT LOG		1. Incident Name Kalamazoo River/Enbridge Oil Spill	2. Date Prepared 10/05/2012	3. Time Prepared 1700
4. Unit Name/Designators Situation Unit		5. Unit Leader (Name and Position) Melinda Leutke, Planning Section Chief		6. Operational Period 0700, 10/04/2012 – 0700, 10/11/2012
7. Personnel Roster Assigned				
Name		ICS Position		Home Base
Larry Rader		Situation Unit Leader		Chicago, Illinois
8. Activity Log				
Time	Major Events			
1030	<p>Boat safety meeting at C0.4 boat launch. Launch.</p> <p>C0.4 boat launch, RI Crews collecting soil sample just east of the C0.4 boat launch.</p> <p>MP 5.6 LDB, sheen sweeper boat observed operating upstream of trestle.</p> <p>MP 5.6 LDB, sheen and tar globules observed along LDB.</p> <p>MP 5.63 RDB, sheen and tar globules observed upstream of trestle near pyramids.</p> <p>Ceresco control point. Crews were in process of removing debris at time of inspection.</p> <p>MP 5.75, sheen observed within debris along Ceresco containment boom.</p> <p>Situation unit collecting water & sediment temperatures along Ceresco Dam containment boom.</p> <p>MP 15.5 South Mill Pond. No sheen or tar globules observed.</p> <p>River channel at North Mill Pond. No sheen observed.</p> <p>Crews observed removing debris from E4.0 control point.</p> <p>North cove on Morrow Lake. No sheen observed in choppy water.</p> <p>South cove of Morrow Lake. No sheen observed in choppy water.</p>			
1430	Finish up inspections at E4.0 boat launch. Return to ICP.			
9. Prepared by (Name and Position) Larry Rader, Situation Unit Leader, USEPA-START				