

US EPA ARCHIVE DOCUMENT

<b>UNIT LOG</b>	1. Incident Name Kalamazoo River/Enbridge Oil Spill	2. Date Prepared 10/09/2012	3. Time Prepared 1915
4. Unit Name/Designators Situation Unit	5. Unit Leader (Name and Position) Mindy Luetke, Planning Section Chief		6. Operational Period 0700, 10/08/2012 – 1540, 10/08/2012
7. Personnel Roster Assigned			
Name		ICS Position	Home Base
Dan Zahner		Situation Unit	St. Louis, MO
8. Activity Log			
Time	Major Events		

0700	<p>River Status</p> <ul style="list-style-type: none"> <li>· MP 5.00 to MP 5.25(C0.4 Boat Launch) RDB: No sheen observed</li> <li>· MP 5.25 to MP 5.75 LDB: Light streamers of silver sheen along with oil globules observed free floating on river segment. Not enough to quantify.</li> <li>· MP 5.60 to control point RDB: Random sheen and oil globules observed free floating on river segment. Area of impact is 10' x 5'.</li> <li>· MP 5.65 (Control Point): Random streamers of silver sheen and oil globules observed at the control point. Area of impact is 100 x 5'. Sheen sweep boat at location performing sheen management.</li> <li>· MP 5.55 RDB (Former submerged oil location): Light streamers of silver sheen observed. Area of impact is 40' x 5'.</li> <li>· MP 8.50 L1: No oil and /or oil sheen observed.</li> <li>· MP 8.50 L2: No oil and /or oil sheen observed.</li> <li>· MP 8.75 R1: No oil and /or oil sheen observed.</li> <li>· MP 10.25: Tree was across the river preventing downstream access. Paul K. called Mike W. to inform him of the river blockage.</li> <li>· MP 10.75 LDB: Not inspected today.</li> <li>· MP 11.79 LDB: Not inspected today.</li> <li>· MP 13.50 LDB: Not inspected today.</li> <li>· C5 Boat Launch (MP 15.00): No oil and /or oil sheen observed on river segment.</li> <li>· MP 15.00 (Mill Ponds): Not inspected today.</li> <li>· MP 19.25 LDB: Not inspected today.</li> <li>· MP 21.50 RDB: One spot of sheen observed from Custer Bridge, not enough to quantify.</li> <li>· MP 23.15 RDB: Not inspected today.</li> <li>· MP 24.75 LDB: Not inspected today.</li> <li>· MP 26.25 LDB: No oil and /or oil sheen observed on river segment.</li> <li>· MP 30.80 LDB: Not inspected today.</li> <li>· MP 36.25 LDB &amp; RDB: No oil and/or oil sheen observed on river segment.</li> <li>· MP 36.50 LDB &amp; RDB: No oil and/or oil sheen observed on river segment.</li> <li>· Delta (Gates C, E, and F): Streamers of silver sheen along with oil globules observed accumulating along hard boom gating system.</li> <li>· E4 to MP 38.754: Very random streamers of silver oil sheen observed in the South Cove area. Too small a area to quantify. No sheen observed in the North Cove or around Rowe Island.</li> </ul>
1520	Return to ICP. End of field day.

9. Prepared by (Name and Position)

Dan Zahner, Situation Unit, USEPA-START