

US EPA ARCHIVE DOCUMENT

<b>UNIT LOG</b>		1. Incident Name Kalamazoo River/Enbridge Oil Spill	2. Date Prepared 10/12/2012	3. Time Prepared 1700
4. Unit Name/Designators Situation Unit		5. Unit Leader (Name and Position) Melinda Leutke, Planning Section Chief		6. Operational Period 0700, 10/11/2012 – 0700, 10/18/2012
7. Personnel Roster Assigned				
Name		ICS Position		Home Base
Matthew Haak		Situation Unit Leader		Houston, TX
8. Activity Log				
Time	Major Events			
0900	<ul style="list-style-type: none"> <li>• Boat safety meeting at E4 boat launch. Launch.</li> <li>• Morrow Lake north cove no sheen observed.</li> <li>• Morrow Lake south cove no sheen observed.</li> <li>• Morrow Lake Delta Gate E no sheen observed.</li> <li>• Morrow Lake Delta Gate C no sheen observed.</li> <li>• MP36.25 Island no sheen observed.</li> <li>• MP26.25 RDB no sheen observed.</li> <li>• MP26.0 RDB Sediment trap no sheen observed.</li> <li>• MP24.75 no sheen was observed.</li> <li>• MP23.1 RDB no sheen observed.</li> <li>• MP30.8 Sediment Trap no sheen observed.</li> <li>• MP21.5 Custer Drive bridge no sheen observed.</li> <li>• MP5.45 LDB spontaneous sheen and tar glob observed.</li> <li>• Ceresco Dam Control Point boom.</li> <li>• Sheen observed collecting along the Ceresco Dam control point boom.</li> </ul>			
1600	Finish up inspections at C0.4 boat launch. Return to ICP.			
9. Prepared by (Name and Position) Matthew Haak, Situation Unit Leader, USEPA-START				