

US EPA ARCHIVE DOCUMENT

UNIT LOG		1. Incident Name Kalamazoo River/Enbridge Oil Spill	2. Date Prepared 10/17/2012	3. Time Prepared 1700
4. Unit Name/Designators Situation Unit		5. Unit Leader (Name and Position) Melinda Leutke, Planning Section Chief		6. Operational Period 0700, 10/11/2012 – 0700, 10/18/2012
7. Personnel Roster Assigned				
Name		ICS Position		Home Base
Matthew Haak		Situation Unit Leader		Houston, TX
8. Activity Log				
Time	Major Events			
0900	<ul style="list-style-type: none"> • Boat safety meeting at C0.4 boat launch. Launch. • MP5.35 ribbons of sheen and tar globs were observed. • MP5.45 RDB sheen and tar globs were observed. • Ceresco Dam Control Point Boom observed a crew removing debris from the boom. • Ceresco Dam Control Point Boom observed sheen collecting along the boom. • Ceresco Dam observed a crew performing weekly maintenance of the Walling Tube Structures. • MP5.70 RDB sheen and tar globs were observed. • MP5.70 RDB sheen and tar globs were observed. • MP5.55RDB area where sheen and tar globs were observed. • MP5.0 RDB area where sheen and tar globs were observed. • MP14.5 LDB sheen and tar globs were observed. • Morrow Lake south cove area where sheen and tar globs were observed. • Morrow Lake south cove sheen and tar globs were observed. • Morrow Lake south cove sheen sweep responding to the sheen and tar globs were observed. • Morrow Lake Delta Gate F observed a crew performing curtain monitoring and adjustments. • Morrow Lake Delta western coved sheen and tar globs were observed. • Morrow Lake Delta western coved sheen and tar globs were observed. • Morrow Lake Delta Gate C no sheen observed. 			
1600	Finish up inspections at E4 boat launch. Return to ICP.			
9. Prepared by (Name and Position) Matthew Haak, Situation Unit Leader, USEPA-START				