

US EPA ARCHIVE DOCUMENT

<b>UNIT LOG</b>		1. Incident Name Kalamazoo River/Enbridge Oil Spill	2. Date Prepared 10/22/2012	3. Time Prepared 1700
4. Unit Name/Designators Situation Unit		5. Unit Leader (Name and Position) Melinda Leutke, Planning Section Chief		6. Operational Period 0700, 10/18/2012 – 0700, 10/25/2012
7. Personnel Roster Assigned				
Name		ICS Position		Home Base
Matthew Haak		Situation Unit Leader		Houston, TX
8. Activity Log				
Time	Major Events			
0900	<ul style="list-style-type: none"> <li>• Boat safety meeting at C0.4 boat launch. Launch.</li> <li>• MP5.0 - MP5.55 LDB area where sheen and tar globs were observed.</li> <li>• MP5.0 LDB sheen and tar globs were observed.</li> <li>• MP5.25 LDB sheen and tar globs were observed.</li> <li>• MP5.35 LDB sheen and tar globs were observed.</li> <li>• MP5.45 LDB sheen and tar globs were observed.</li> <li>• MP5.63 LDB area where and sheen and tar globs were observed.</li> <li>• MP5.63 LDB area where and sheen and tar globs were observed.</li> <li>• Ceresco Dam Control Point Boom observed sheen and tar globs collecting along the boom.</li> <li>• Ceresco Dam Control Point Boom observed sheen and tar globs collecting along the boom.</li> <li>• Ceresco Dam control point boom observed a crew removing debris from the control point boom.</li> <li>• Ceresco Dam upstream end of the control point boom observed sheen collecting along the boom.</li> <li>• MP4.75 LDB area where sheen was observed.</li> <li>• MP4.75 LDB area where sheen was observed.</li> <li>• MP8.5 LDB observed the RI crew working.</li> <li>• MP10.75 Sediment trap sheen and tar glob observed.</li> <li>• MP14.5 LDB Area where sheen was observed.</li> <li>• MP14.5 LDB sheen was observed.</li> <li>• MP15.5 South Mill Pond ribbons of sheen were observed.</li> <li>• MP15.5 South Mill Pond ribbons of sheen and tar globs were observed.</li> <li>• MP15.0 LDB South Mill Pond area where ribbons of sheen were observed.</li> <li>• MP11.79 Back channel sediment trap.</li> </ul>			

	<ul style="list-style-type: none"><li>· Morrow Lake E4 Boat launch sheen observed.</li><li>· Morrow Lake Delta Gate F observed sheen collecting along the boom.</li><li>· Morrow Lake Delta Gate E observed sheen collecting along the boom.</li><li>· Morrow Lake Delta observed the poling team.</li><li>· MP36.5 Boat agitated sheen.</li></ul>
1600	Finish up inspections at E4 boat launch. Return to ICP.
9. Prepared by (Name and Position) Matthew Haak, Situation Unit Leader, USEPA-START	