

US EPA ARCHIVE DOCUMENT

UNIT LOG		1. Incident Name Kalamazoo River/Enbridge Oil Spill	2. Date Prepared 10/27/2012	3. Time Prepared 1700
4. Unit Name/Designators Situation Unit		5. Unit Leader (Name and Position) Melinda Leutke, Planning Section Chief		6. Operational Period 0700, 10/25/2012 – 0700, 11/1/2012
7. Personnel Roster Assigned				
Name		ICS Position		Home Base
Matthew Haak		Situation Unit Leader		Houston, TX
8. Activity Log				
Time	Major Events			
0900	<ul style="list-style-type: none"> • Boat safety meeting at C0.4 boat launch. Launch. • Morrow Lake North Cove no sheen observed • Morrow Lake hunter observed between Rowe Island and the little island. • Morrow Lake south cove sheen and tar globs observed. • Morrow Lake Delta observed sheen and tar globs collecting along Gate E. • Morrow Lake Delta Gate C observed sheen and tar globs collecting along the boom. • Morrow Lake Fan observed the sweep boat operating. • MP26.25 no sheen observed. • MP26.0 Sediment Trap boat generated sheen observed. • MP24.75 no sheen observed • MP23.10 no sheen observed • MP27.75 no sheen observed • MP30.8 no sheen observed • MP21.5 Custer Bridge no sheen observed. • MP15.5 Burnham St Bridge no sheen observed • MP5.15 LDB sheen and tar globs observed. • MP5.45 LDB sheen and tar globs observed. • MP5.63 LDB sheen and tar globs observed. • Observed sheen and tar globs collecting along the Ceresco Dam Control Point Boom. • Ceresco Dam Control Point Boom boat generated sheen. 			
1500	Finish finished. Return to ICP.			
9. Prepared by (Name and Position) Matthew Haak, Situation Unit Leader, USEPA-START				