

US EPA ARCHIVE DOCUMENT

UNIT LOG		1. Incident Name Kalamazoo River/Enbridge Oil Spill	2. Date Prepared 10/29/2012	3. Time Prepared 1700
4. Unit Name/Designators Situation Unit		5. Unit Leader (Name and Position) Melinda Leutke, Planning Section Chief		6. Operational Period 0700, 10/25/2012 – 0700, 11/1/2012
7. Personnel Roster Assigned				
Name		ICS Position		Home Base
Larry Rader		Situation Unit Leader		Chicago, Illinois
8. Activity Log				
Time	Major Events			
0900	<ul style="list-style-type: none"> • Boat safety meeting at C0.4 boat launch. Launch. • MP4.5 river channel, boat generated sheen and tar globules observed. • MP5.25 LDB, sheen sweeper boat observed. • MP5.75 RDB, spontaneous sheen and tar globule observed. • MP5.75 RDB, boat generated sheen and tar globules observed. • Ceresco Dam, observed sheen and tar globules collecting within debris along the boom. • MP15.00 Mill Ponds, no sheen observed in river channel. • North Cove of Morrow Lake, high winds & choppy water observed on lake, no sheen observed in North Cove. • Poling crews observed delineating points in Morrow Lake fan. Crews were reporting mostly light & moderate poling results from delineation points. • South Cove of Morrow Lake, high winds observed, no sheen observed in white caps in South Cove. 			
1530	Return to ICP.			
9. Prepared by (Name and Position) Larry Rader, Situation Unit Leader, USEPA-START				