

US EPA ARCHIVE DOCUMENT

UNIT LOG		1. Incident Name Kalamazoo River/Enbridge Oil Spill	2. Date Prepared 11/20/2012	3. Time Prepared 1800
4. Unit Name/Designators Situation Unit		5. Unit Leader (Name and Position) Melinda Luetke, Planning Section Chief		6. Operational Period 0700, 11/5/2012 – 0700, 11/27/2012
7. Personnel Roster Assigned				
Name		ICS Position		Home Base
Larry Rader		Situation Unit Leader		Chicago, IL
8. Activity Log				
Time	Major Events			
09:30	<ul style="list-style-type: none"> • Boat safety meeting at C0.4 boat launch. Launch. • MP 5.5 river channel, sheen observed following agitation of sediments by boat. Boat had to back up in river channel. • MP 5.75 LDB, sheen observed just downstream from trestle above Ceresco Dam. • Ceresco Dam control point boom, observed sheen and debris collecting along the boom. • MP15.5 RDB Burnham Street bridge, excavation trench box used for utility installation is still in place in river, with containment boom installed around it. Sheen and tar globules were observed within the containment boom around the trench box. • Morrow Lake Delta, booms A, B, C1 and C2 have been removed. Crews were observed towing boom from delta in to E4.0 boat launch. • Crews observed dismantling containment boom and tying it up in bundles for loading into roll-off box for transport & disposal. • Morrow Lake north cove, no sheen or ice observed. 			
14:30	Returned to Boat Launch E4.0. Return to ICP.			
9. Prepared by (Name and Position) Larry Rader, Situation Unit Leader, USEPA-START				