

US EPA ARCHIVE DOCUMENT

UNIT LOG		1. Incident Name Kalamazoo River/Enbridge Oil Spill	2. Date Prepared 11/26/2012	3. Time Prepared 1700
4. Unit Name/Designators Situation Unit		5. Unit Leader (Name and Position) Melinda Luetke, Planning Section Chief		6. Operational Period 0700, 11/5/2012 – 0700, 11/27/2012
7. Personnel Roster Assigned				
Name		ICS Position		Home Base
Larry Rader		Situation Unit Leader		Chicago, IL
8. Activity Log				
Time	Major Events			
07:45	<ul style="list-style-type: none"> Arrive at ICP 			
10:00	<ul style="list-style-type: none"> Arrived C0.4 boat launch, no ice or sheen observed. MP5.63 RDB observed a very thin layer of ice forming on downstream side of trestle. Ceresco Dam control point boom, some sheen observed within debris in containment. Ceresco Dam control point, no ice observed forming along the boom. Ceresco Dam impoundment, no ice observed forming along the LDB. MP5.5 LDB observed no ice forming along the river bank. MP15.5 South Mill Pond, observed ice forming in eastern portion of Mill Pond. MP15.5 North Mill Pond, observed utility work continuing on northern side of Burnham Street Bridge. No sheen observed. Morrow Lake Delta, no ice observed forming within the neck of the delta. Morrow Lake Delta, observed the anchor poles and boom in place. 			
15:45	<ul style="list-style-type: none"> MP 17.00 RDB, inspected sheen area reported by City of Battle Creek. Sheen was confirmed to be biogenic by stick test. 			
16:30	Return to ICP. Prepare photo log and 214.			
9. Prepared by (Name and Position) Larry Rader, Situation Unit Leader, USEPA-START				