

US EPA ARCHIVE DOCUMENT

UNIT LOG		1. Incident Name Kalamazoo River/Enbridge Oil Spill	2. Date Prepared 11/27/2012	3. Time Prepared 1800
4. Unit Name/Designators Situation Unit		5. Unit Leader (Name and Position) Melinda Luetke, Planning Section Chief		6. Operational Period 0700, 11/27/2012 – 0700, 12/10/2012
7. Personnel Roster Assigned				
Name		ICS Position		Home Base
Larry Rader		Situation Unit Leader		Chicago, IL
8. Activity Log				
Time	Major Events			
09:30	<ul style="list-style-type: none"> • Arrived at C0.4 boat launch. • No sheen observed in vicinity of trestle above Ceresco Dam. Bank ice observed along LDB and RDB on upstream and downstream sides of trestle. 			
12:30	<ul style="list-style-type: none"> • Bank ice observed along LDB near portage on upstream side of Ceresco Dam • No sheen, some debris observed within Ceresco Dam containment boom. • Ice observed in backchannel areas of Mill Ponds. Utility crews continue to work on Burnham Street west of river. Trench box remains in river on north side of Burnham Street Bridge. 			
11:30	<ul style="list-style-type: none"> • Return to ICP. 			
13:00	<ul style="list-style-type: none"> • Boarded the helicopter for the weekly flight. • Source area, observed ice on standing water at Source Area. • Talmadge Creek, observed the new line 6B work. • Frac-Tank decontamination pad, observed crews construction shelter next to decon pad. • Ceresco Dam control point, observed bathymetry survey crews operating along LDB below trestle. • MP15.5, observed utility crews excavating in river near Burnham Street bridge. • MP21.25 oxbow, no sheen or ice observed. • MP 28.25 oxbow, no sheen or ice observed. • Morrow Lake Delta, boom anchors remain in place. • Observed two sweeper boats operating in North Cove in Morrow Lake. • Morrow Dam, no sheen or activity observed. 			
14:30	Returned to Brooks Field.			
9. Prepared by (Name and Position) Larry Rader, Situation Unit Leader, USEPA-START				