

US EPA ARCHIVE DOCUMENT

Situation Photo Log

Monday, December 3, 2012

Kalamazoo River / Enbridge Spill

Water / Sediment Temperatures

Location	Water Temp. (°F)	Sediment Temp. (°F)
C0.4 Boat Launch Gauge	47.28	46.44
Ceresco Dam Control Point Boom	46.18	45.16
C3.2 Boat Launch Gauge	46.65	45.87
C5 Boat Launch Gauge	46.27	45.46
E4 Boat Launch Gauge	48.18	46.46



1. C0.4 Boat launch observed sheen and tar globs.



2. MP5.25 LDB sheen and tar globs observed.



3. MP5.45 LDB sheen and tar globs observed.



4. MP5.63 LDB sheen and tar globs observed. Sheen sweep was requested.



5. MP5.63 LDB sheen and tar globs observed. Sheen sweep was requested.



6. Ceresco Dam impoundment observed two bathymetry teams.



7. Ceresco Dam impoundment observed two bathymetry teams.




8. Ceresco Dam impoundment observed two bathymetry teams.



9. Ceresco Dam Control Point boom observed sheen and tar globs collecting along the boom.



10. Ceresco Dam Control Point boom observed sheen and tar globs collecting along the boom.



11. Ceresco Dam impoundment observed sheen and tar globs within the center channel.



12. Observed the sheen sweep responding to the sheen at MP5.63 LDB.



13. MP5.55 Railroad trestles observed sheen.



14. MP4.5 area where sheen and tar globs were observed within the center channel of the river.



15. MP4.5 sheen and tar globs observed in the center channel of the river.
Sheen response requested.



16. MP4.5 sheen and tar globs observed in the center channel of the river.
Sheen response requested.



17. MP10.75 Sediment trap observed a RI Crew.



18. MP10.75 Sediment Trap observed sheen collecting.



19. MP15.5 South Mill Pond no sheen observed.



20. MP15.5 Burnham Street Bridge utility work continued, new obstructions observed in the river channel.



21. MP15.65 LDB observed sheen and tar globs.



22. Morrow Lake north cove observed a sweep boat operating.



23. Morrow Lake observed a poling crew.



24. Morrow Lake poling team observed.



25. Morrow Lake south cove observed sheen.



26. Morrow Lake south cove observed sheen.