

US EPA ARCHIVE DOCUMENT

| | | | | |
|--|--|--|--------------------------------|---|
| UNIT LOG | | 1. Incident Name Kalamazoo River/Enbridge Oil Spill | 2. Date Prepared 12/13/2012 | 3. Time Prepared 1700 |
| 4. Unit Name/Designators Situation Unit | | 5. Unit Leader (Name and Position) Melinda Luetke, Planning Section Chief | | 6. Operational Period 0700, 12/10/2012 – 0700, 12/22/2012 |
| 7. Personnel Roster Assigned | | | | |
| Name | | ICS Position | | Home Base |
| Matthew Haak | | Situation Unit Leader | | Houston |
| 8. Activity Log | | | | |
| Time | Major Events | | | |
| 0800 | <ul style="list-style-type: none"> • Attended the internal C&G meeting | | | |
| 0900 | <ul style="list-style-type: none"> • Arrived at C0.4 Boat launch. • MP5.60 LDB ice observed forming. • MP5.63 LDB ice observed forming above the railroad trestles. • MP5.63 LDB ice observed forming below the railroad trestles. • Ceresco Dam impoundment observed a bathymetry team. • MP5.89 LDB sheen observed. • Ceresco Dam control point boom observed a very thin layer of ice forming. • MP5.63 – MP5.70 RDB observed ice forming. • Observed core logging. • MP10.75 observed a bathymetry team. • MP12.5 RDB observed an RI crew. • MP15.25 South Mill Pond observed ice forming. • MP15.25 South Mill Pond observed sheen and tar globs frozen in the ice. • MP21.5 Sediment trap observed a bathymetry team. • MP21.5 Sediment trap observed a bathymetry team. • Morrow Lake north and south coves no sheen observed. • Morrow Lake Delta no sheen observed. • Morrow Lake Delta A observed a bathymetry team and a CSD sampling team. | | | |
| 1600 | Returned to ICP. | | | |
| 9. Prepared by (Name and Position) Matthew Haak, Situation Unit Leader, USEPA-START | | | | |