

US EPA ARCHIVE DOCUMENT

UNIT LOG		1. Incident Name Kalamazoo River/Enbridge Oil Spill	2. Date Prepared 01/15/2013	3. Time Prepared 1500
4. Unit Name/Designators Situation Unit		5. Unit Leader (Name and Position) Melinda Luetke, Planning Section Chief		6. Operational Period 0700, 1/14/2013 – 0700, 1/28/2013
7. Personnel Roster Assigned				
Name		ICS Position		Home Base
Matthew Haak		Situation Unit Leader		Houston, TX
8. Activity Log				
Time	Major Events			
0800	<ul style="list-style-type: none"> • Attended the EPA C&G meeting. 			
0900	<ul style="list-style-type: none"> • Arrived at the C0.4 Boat Launch. All boats were canceled for the day. • C0.4 Boat launch observed sheets of ice flowing within the river. • Ceresco Dam impoundment icing conditions • Observed core logging in the C3.2 pole barn • C3.2 Boat launch observed sheets of ice flowing within the river • MP15.25 South Mill Pond observed ice forming • MP15.25 South Mill Ponds observed sheets of ice flowing within the river. • MP19.0 LDB observed an RI crew. • MP21.5 Custer bridge observed turbidity in the river. No ice observed flowing within the river. • MP21.5 Oxbow observed the buoys dislodged. • MP27.0 Shadybend Campground river conditions. No ice observed flowing within the river. • E2 Boat launch no ice observed flowing within the river. • Morrow Lake observed ice forming. • Morrow Lake Delta observed bank ice forming. • Morrow Lake Delta observed sheen frozen within the ice. • MP36.5 35th Street Bridge no ice observed flowing within the river. 			
1200	Returned to ICP.			
9. Prepared by (Name and Position) Matthew Haak, Situation Unit Leader, USEPA-START				