

US EPA ARCHIVE DOCUMENT



# Situation Update

January 16, 2013

# Submerged Oil Science



- Former E-4 Containment system post removal bathymetry resumed and completed during this period.



01.10.2013 Bathymetry crews at the former E4.0 Containment system.

# Submerged Oil Science



- Former E-4 Containment system post removal bathymetry resumed and completed during this period.



01.12.2013 Bathymetry Survey crews at the Former E-4 Containment System

# Emerging Oil Management

Ceresco – MP 5.50 LDB

01.11.2013

Spontaneous sheen and tar globules



# Emerging Oil Management

Ceresco – MP 5.25 LDB

01.12.2013

Spontaneous sheen and tar globules



# Emerging Oil Management

Ceresco – MP 5.60 RDB

01.12.2013

Spontaneous sheen and tar globules



# Emerging Oil Management

Ceresco – MP 5.70 RDB

01.14.2013

Spontaneous sheen and tar globules



# River Icing Conditions

Thawing Ice Conditions

01.10.2013

Morrow Lake Delta



# River Icing Conditions

Thawing Ice Conditions

01.10.2013

Morrow Lake



# River Icing Conditions

Thawing Ice Conditions

01.10.2013

Ceresco Dam Impoundment



# River Icing Conditions

Thawing Ice Conditions

01.14.2013

Morrow Lake



# River Icing Conditions

Thawing Ice Conditions

01.14.2013

Morrow Lake Delta



# River Icing Conditions

Thawing Ice Conditions

01.14.2013

Ceresco Dam Impoundment



# River Icing Conditions

01.14.2013

Enbridge suspended work due to icy  
boat ramps



# River Icing Conditions

01.15.2013

Enbridge suspended work due to Frazil  
and bank ice

