

US EPA ARCHIVE DOCUMENT

UNIT LOG		1. Incident Name Kalamazoo River/Enbridge Oil Spill	2. Date Prepared 01/18/2013	3. Time Prepared 1500
4. Unit Name/Designators Situation Unit		5. Unit Leader (Name and Position) Melinda Luetke, Planning Section Chief		6. Operational Period 0700, 1/14/2013 – 0700, 1/28/2013
7. Personnel Roster Assigned				
Name		ICS Position		Home Base
Matthew Haak		Situation Unit Leader		Houston, TX
8. Activity Log				
Time	Major Events			
0800	<ul style="list-style-type: none"> • Attended the EPA C&G meeting. • Source area observed a crew collecting soil cores. • Source area observed a crew collecting soil cores. • Ceresco Dam impoundment observed bank ice reforming. • MP5.8 RDB observed tar globs and sheen frozen in the ice. • MP5.75 RDB observed bank reforming. • MP5.63 RDB observed bank ice reforming. • C0.4 Boat launch staff gauge observed sheen along the ice. • C0.4 Boat launch observed sheen along the ice. • C3.2 pole barn observed core logging. • MP15.25 South Mill Pond observed ice reforming. • MP15.25 South Mill Pond observed a tar glob and sheen frozen in the ice. • MP19.5 LDB observed the RI crew. • E4 Boat Launch Morrow Lake observed ice reforming. • Morrow Lake Delta/Morrow Lake Neck no ice observed. • Morrow Lake Delta no ice observed from the 35th Street Bridge. • MP36.5 RDB Upstream side of the 35th Street Bridge observed sheen. • Morrow Lake Delta observed bank ice forming around the islands. 			
1200	Returned to ICP.			
9. Prepared by (Name and Position) Matthew Haak, Situation Unit Leader, USEPA-START				