

US EPA ARCHIVE DOCUMENT

UNIT LOG		1. Incident Name Kalamazoo River/Enbridge Oil Spill	2. Date Prepared 01/24/2013	3. Time Prepared 1600
4. Unit Name/Designators Situation Unit		5. Unit Leader (Name and Position) Melinda Luetke, Planning Section Chief		6. Operational Period 0700, 1/14/2013 – 0700, 1/28/2013
7. Personnel Roster Assigned				
Name		ICS Position		Home Base
Matthew Haak		Situation Unit Leader		Houston, TX
8. Activity Log				
Time	Major Events			
0900	<ul style="list-style-type: none"> • Attended the EPA C&G meeting. 			
09:45	<ul style="list-style-type: none"> • C0.4 Boat launch observed river icing conditions. • MP5.25 C0.4 observed river icing conditions. • Ceresco Dam impoundment observed river icing conditions. • C3.2 Pole Barn observed core logging operations. • C3.2 Boat launch observed river icing conditions. • MP10.35 Observed river icing conditions. • MP15.25 South Mill Pond observed river icing conditions. • MP15.5 North Mill Pond observed river icing conditions. • MP19.25 observed river icing conditions. • MP21.5 observed the oxbow river icing conditions. • E2 Boat launch observed river icing conditions. • MP27.0 E0.5 Boat launch observed river icing conditions. • MP27.0 E0.5 Boat launch observed river icing conditions. • Morrow Lake observed icing conditions. • Morrow Lake Neck/Morrow Lake Delta observed icing conditions. • Morrow Lake Delta observed icing conditions. • MP21.25 RDB overbank oxbow observed the RI crew. • MP21.25 RDB overbank oxbow observed sheen in the core hole. • MP14.0 Beadle Lake Rd. Bridge downstream observed river icing conditions. • MP14.0 Beadle Lake Rd. Bridge upstream observed river icing conditions. 			
1400	Returned to ICP.			
9. Prepared by (Name and Position) Matthew Haak, Situation Unit Leader, USEPA-START				