

US EPA ARCHIVE DOCUMENT

UNIT LOG		1. Incident Name Kalamazoo River/Enbridge Oil Spill	2. Date Prepared 01/26/2013	3. Time Prepared 1600
4. Unit Name/Designators Situation Unit		5. Unit Leader (Name and Position) Melinda Luetke, Planning Section Chief		6. Operational Period 0700, 1/14/2013 – 0700, 1/28/2013
7. Personnel Roster Assigned				
Name		ICS Position		Home Base
Matthew Haak		Situation Unit Leader		Houston, TX
8. Activity Log				
Time	Major Events			
09:30	<ul style="list-style-type: none"> • C0.4 Boat launch observed upstream river icing conditions. • Ceresco Dam impoundment observed river icing conditions. • MP9.75 Downstream from Waddles Bridge observed river conditions. • MP9.75 Upstream from Waddles Bridge observed river conditions. • C3.2 Boat launch observed river icing conditions. River levels appeared to be dropping. • MP15.25 South Mill Pond observed river icing conditions. • MP15.25 South Mill Pond observed river icing conditions. • MP15.5 North Mill Pond observed river icing conditions. • MP21.5 Oxbow observed river icing conditions. • MP21.5 observed river icing conditions. • E2 Boat launch observed river icing conditions. River levels appeared to be dropping. • MP27.0 E0.5 Boat launch observed river icing conditions. • Morrow Lake observed icing conditions. • Morrow Lake Neck/Morrow Lake Delta observed icing conditions. • Morrow Lake Delta observed icing conditions. 			
1400	Returned to ICP.			
9. Prepared by (Name and Position) Matthew Haak, Situation Unit Leader, USEPA-START				