

US EPA ARCHIVE DOCUMENT

UNIT LOG	1. Incident Name Kalamazoo River/Enbridge Oil Spill	2. Date Prepared 02/04/2013	3. Time Prepared 1700
4. Unit Name/Designators Situation Unit	5. Unit Leader (Name and Position) Mindy Luetke, Planning Section Chief	6. Operational Period 0800, 02/04/13 – 1600, 02/04/13	
7. Personnel Roster Assigned			
Name		ICS Position	Home Base
Karen Berecz		Situation Unit 2	Dallas, TX
8. Activity Log			
Time	Major Events		

0800	Situation Unit Observations: · Arrive at ICP. · Attend daily EPA/START daily command and general staff meeting. · Arrive at C0.4 Boat Launch. Observed river icing conditions. A narrow segment of river channel remains open. · Arrive at Ceresco Dam impoundment. Observed river icing conditions. River channel remains open. No ice observed flowing in river channel. · Arrive at Ceresco Dam. Observed river icing conditions. No ice observed flowing over dam. · Arrive at C3.2 Pole Barn observed core logging procedures. · Arrive at MP13.50 RDB observed the RI team collect soil cores from overbank. Observed river icing conditions. Observed ice flowing on river channel. · Arrive at MP13.75 RDB observed the RI team collect soil cores from overbank. · Arrive at C3.2 Boat Launch. Observed river icing conditions. No ice observed flowing in river channel. · Arrive at Mill Ponds. Observed South Mill Pond river and back water area icing conditions. Observed ice flowing on river channel, and back water area covered in ice and snow. Observed North Mill Pond river and back water area icing conditions. Observed ice flowing on river channel, and back water area covered in ice and snow. River channel at culverts remains open. · Arrive at MP21.50. Observed river and oxbow icing conditions. Observed ice flowing on river channel, and oxbow almost entirely covered with ice and snow. · Arrive at E2 Boat Launch. Observed river icing conditions. Observed ice flowing on river channel. · Arrive at MP27.00 Shady Bend Campground. Observed river icing conditions. Observed ice flowing on river channel. · Arrive at E4 Boat Launch. Observed icing conditions in the Morrow Lake Neck/Morrow Lake Delta and Morrow Lake. Observed Morrow Lake Neck/Delta completely covered with ice and snow. Observed a narrow open water area on Morrow Lake just south of the boat launch. · Arrive at Morrow Lake Delta. Observed icing conditions. Delta completely covered with ice and snow. · Arrive at MP2.25 Saylor's Landing. Observed river icing conditions. No ice observed flowing on river channel. · Arrive at the Confluence. No ice observed along Talmadge Creek leading to the confluence. Observed ice at confluence area. No ice observed flowing on river channel.
1600	· Arrive at ICP. End of field day.

9.	Prepared by (Name and Position) Karen Berecz, Situation Unit, USEPA-START
----	--