

US EPA ARCHIVE DOCUMENT

UNIT LOG		1. Incident Name Kalamazoo River/Enbridge Oil Spill	2. Date Prepared 02/14/2013	3. Time Prepared 1600
4. Unit Name/Designators Situation Unit		5. Unit Leader (Name and Position) Melinda Luetke, Planning Section Chief		6. Operational Period 0700, 2/11/2013 – 0700, 2/25/2013
7. Personnel Roster Assigned				
Name		ICS Position		Home Base
Matthew Haak		Situation Unit Leader		Houston, TX
8. Activity Log				
Time	Major Events			
09:45	<ul style="list-style-type: none"> Overflight canceled because of potential freezing rain conditons. 			
10:15	<ul style="list-style-type: none"> C0.4 Boat launch met up with Enbridge counterpart. C0.4 Boat launch observed river icing conditions. MP5.10 C0.4 Boat launch sheen and tar globs observed. MP5.25 RDB sheen and tar globs observed. MP5.25 LDB sheen and tar globs observed. MP5.63 Ceresco Dam impoundment observed icing conditions. Ceresco Dam impoundment observed icing conditions. MP5.35 RDB sheen and tar globs observed. MP5.30 RDB sheen and tar globs observed. MP5.89 RDB observed a bio film. MP5.89 RDB sheen and tar glob observed. C3.2 Boat launch observed crews preparing to repair the damaged MP10.75 sediment trap tree structure. MP15.25 South Mill Pond observed river icing conditions. MP15.25 South Mill Pond observed sheen. MP15.75 North Mill Pond observed river icing conditions. MP15.75 Battle Creek Spillway observed river icing conditions. MP21.5 Sediment trap river observed icing conditions. Morrow Lake observed icing conditions. Morrow Lake Delta neck observed icing conditions. Morrow Lake Delta observed icing conditions. 			
1600	Returned to ICP.			
9. Prepared by (Name and Position) Matthew Haak, Situation Unit Leader, USEPA-START				