

US EPA ARCHIVE DOCUMENT

UNIT LOG		1. Incident Name Kalamazoo River/Enbridge Oil Spill	2. Date Prepared 02/21/2013	3. Time Prepared 1600
4. Unit Name/Designators Situation Unit		5. Unit Leader (Name and Position) Melinda Luetke, Planning Section Chief		6. Operational Period 0700, 2/11/2013 – 0700, 2/25/2013
7. Personnel Roster Assigned				
Name		ICS Position		Home Base
Matthew Haak		Situation Unit Leader		Houston, TX
8. Activity Log				
Time	Major Events			
0900	<ul style="list-style-type: none"> • Attended the EPA C&G meeting. 			
1000	<ul style="list-style-type: none"> • Attended safety briefing. 			
11:15	<ul style="list-style-type: none"> • Arrived at C0.4 Boat launch and met up with my Enbridge counterpart. • C0.4 Boat launch river icing conditions observed. • MP5.75 Ceresco Dam impoundment river icing conditions observed. • MP5.63 Ceresco Dam impoundment river icing conditions observed. • Ceresco Dam impoundment river icing conditions observed. • C3.2 Pole Barn observed core logging. • C3.2 Observed river icing conditions. • MP15.25 South Mill Pond river icing conditions observed. • MP15.75 North Mill Pond river icing conditions observed. • MP21.5 River icing conditions observed. • MP21.5 Sheen observed in a pocket of melted ice. • MP27.0 Shady Bend Campground river conditions observed. • E2 Boat launch observed river conditions. • Morrow Lake icing conditions observed. • Morrow Lake Delta Neck river icing conditions observed. • Morrow Lake Delta river icing conditions observed. • Morrow Lake Delta sheen observed in a pool of melted ice. 			
1500	Returned to ICP.			
9. Prepared by (Name and Position) Matthew Haak, Situation Unit Leader, USEPA-START				