

US EPA ARCHIVE DOCUMENT

UNIT LOG		1. Incident Name Kalamazoo River/Enbridge Oil Spill	2. Date Prepared 01/14/2013	3. Time Prepared 1700
4. Unit Name/Designators Situation Unit		5. Unit Leader (Name and Position) Melinda Luetke, Planning Section Chief		6. Operational Period 0700, 1/14/2013 – 0700, 1/28/2013
7. Personnel Roster Assigned				
Name		ICS Position		Home Base
Matthew Haak		Situation Unit Leader		Houston, TX
8. Activity Log				
Time	Major Events			
0800	<ul style="list-style-type: none"> Attended the EPA C&G meeting. 			
0900	<ul style="list-style-type: none"> Arrived at the C0.4 Boat Launch. All boats were canceled for the day. Inspected the boat ramp condition. Observed snow and deminimus ice formation on the boat ramp. MP5.73 RDB slushy ice observed forming along the RDB. MP5.70 RDB sheen and tar globs observed within the vegetation and ice. LDB above Ceresco Dam observed ice forming. MP5.80 RDB above Ceresco Dam observed a noise monitoring station. RDB above Ceresco Dam no ice or sheen observed. Observed core logging in the C3.2 pole barn. C3.2 Boat launch, observed snow and deminimus ice formation on the boat ramp. MP15.25 South Mill Ponds no sheen observed. MP15.25 South Mill Ponds observed ice forming along the bank. MP19.0 RDB observed an RI crew. D2 Boat launch, observed snow and deminimus ice formation on the boat ramp. E0.5 Boat launch, observed snow and deminimus ice formation on the boat ramp. E2 Boat Launch observed a goose hunter. Observed snow and deminimus ice formation on the boat ramp. E4 Boat launch, observed snow and deminimus ice formation on the boat ramp. Morrow Lake no ice or sheen observed. Morrow Lake Delta no ice or sheen observed. 			
1200	Returned to ICP.			
9. Prepared by (Name and Position) Matthew Haak, Situation Unit Leader, USEPA-START				