

Dear Aimee,

Thank you very much for taking the time to discuss DCP's comments this morning. There were 2 items which were discussed which need to be captured in this communication:

1. Per your request, you needed DCP to submit a request to revise the language associated with the Trace Erase System to indicate instead an "analyzer catalytic oxidizer system such as Trace Erase or the equivalent".

2. As we discussed, I noticed an error in DCP's comments in the Project Description of the SOB. DCP proposed "The facility throughput may exceed 75,000 bpd and is dependent on the inlet NGL composition without exceeding the CO2e emissions estimated in the GHG PSD permit application."

DCP notes that **the facility** should identify **each train of the facility** and therefore requests the proposed language to be modified to *"The throughput of an individual train may exceed 75,000 bpd and is dependent on the inlet NGL composition without exceeding the CO2e emissions estimated in the GHG PSD permit application." This same comment is applicable to the Draft GHG PSD permit where in the fourth sentence of the Project Description, DCP also suggested <i>"The facility throughput."*. Please revise to *"The throughput of an individual train may not exceed..."*

If there are any other issues that need to be addressed, please let me know or if the above in insufficient, don't hesitate to contact me.

Sincerely,

Lynn Holt Senior Environmental Specialist DPC Midstream, LP Arklatex / Gulf Coast Assets

(o) 903-694-4114 (c) 903-754-0945 This Email message contained an attachment named image001.jpg which may be a computer program. This attached computer program could contain a computer virus which could cause harm to EPA's computers, network, and data. The attachment has been deleted.

This was done to limit the distribution of computer viruses introduced into the EPA network. EPA is deleting all computer program attachments sent from the Internet into the agency via Email.

If the message sender is known and the attachment was legitimate, you should contact the sender and request that they rename the file name extension and resend the Email with the renamed attachment. After receiving the revised Email, containing the renamed attachment, you can rename the file extension to its correct name.

For further information, please contact the EPA Call Center at (866) 411-4EPA (4372). The TDD number is (866) 489-4900.