


US EPA ARCHIVE DOCUMENT

# KPDES FORM 1



## KENTUCKY POLLUTANT DISCHARGE ELIMINATION SYSTEM

### PERMIT APPLICATION

This is an application to: (check one)

- Apply for a new permit.
- Apply for reissuance of expiring permit.
- Apply for a construction permit.
- Modify an existing permit.

Give reason for modification under Item II.A.

A complete application consists of this form and one of the following:

Form A, Form B, Form C, Form F, or Short Form C

**For additional information contact:**

**KPDES Branch (502) 564-3410**

<b>I. FACILITY LOCATION AND CONTACT INFORMATION</b>	AGENCY USE						
---	------------	--	--	--	--	--	--

A. Name of business, municipality, company, etc. requesting permit <b>Sidney Coal Company, Inc.</b>	
B. Facility Name and Location Facility Location Name: <b>Fraley Branch Surface Mine</b>	C. Facility Owner/Mailing Address Owner Name: <b>Sidney Coal Company, Inc.</b>
Facility Location Address (i.e. street, road, etc.): <b>Near the junction of KY 468 and KY 612</b>	Mailing Street: <b>P. O. Box 299</b>
Facility Location City, State, Zip Code: <b>Sidney, KY 41564</b>	Mailing City, State, Zip Code: <b>Sidney, KY 41564</b>
	Telephone Number: <b>(606) 353-7201</b>

<b>II. FACILITY DESCRIPTION</b>
---------------------------------

A. Provide a brief description of activities, products, etc: <b>This permit modification (898-0672 Amendment 3) involves the addition of additional acreage, including one hollow fill, one embankment pond, and eight on-bench ponds to the Fraley Branch Surface Mine for use in a surface coal mining project.</b>	
B. Standard Industrial Classification (SIC) Code and Description	
Principal SIC Code & Description:	<b>1221 – Bituminous Coal &amp; Lignite Mining</b>
Other SIC Codes:	

<b>III. FACILITY LOCATION</b>
-------------------------------

A. Attach a U.S. Geological Survey 7 ½ minute quadrangle map for the site. (See instructions)	
B. County where facility is located: <b>Pike</b>	City where facility is located (if applicable):
C. Body of water receiving discharge: <b>Spring Branch</b>	
D. Facility Site Latitude (degrees, minutes, seconds): <b>37° 40' 28" N</b>	Facility Site Longitude (degrees, minutes, seconds): <b>82° 22' 39" W</b>
E. Method used to obtain latitude & longitude (see instructions):	<b>Topographic map coordinates</b>
F. Facility Dun and Bradstreet Number (DUNS #) (if applicable):	

US EPA ARCHIVE DOCUMENT

**IV. OWNER/OPERATOR INFORMATION**

A. Type of Ownership:

Publicly Owned  Privately Owned  State Owned  Both Public and Private Owned  Federally owned

B. Operator Contact Information (See instructions)

Name of Treatment Plant Operator: <b>Sidney Coal Company, Inc.</b>	Telephone Number: <b>(606) 353-7201</b>
---	--

Operator Mailing Address (Street):  
**P. O. Box 299**

Operator Mailing Address (City, State, Zip Code):  
**Sidney, KY 41564**

Is the operator also the owner?  
Yes  No

Is the operator certified? If yes, list certification class and number below.  
Yes  No

Certification Class:

Certification Number:

**V. EXISTING ENVIRONMENTAL PERMITS**

Current NPDES Number: <b>KYG045956</b>	Issue Date of Current Permit:	Expiration Date of Current Permit:
Number of Times Permit Reissued:	Date of Original Permit Issuance:	Sludge Disposal Permit Number:
Kentucky DOW Operational Permit #:	Kentucky DSMRE Permit Number(s): <b>898-0672 A3</b>	

C. Which of the following additional environmental permit/registration categories will also apply to this facility?

CATEGORY	EXISTING PERMIT WITH NO.	PERMIT NEEDED WITH PLANNED APPLICATION DATE
Air Emission Source		
Solid or Special Waste		
Hazardous Waste - Registration or Permit		

**VI. DISCHARGE MONITORING REPORTS (DMRs)**

KPDES permit holders are required to submit DMRs to the Division of Water on a regular schedule (as defined by the KPDES permit). The information in this section serves to specifically identify the department, office or individual you designate as responsible for submitting DMR forms to the Division of Water.

A. Name of department, office or official submitting DMRs:	<b>Randy Tackett, Agent</b>
B. Address where DMR forms are to be sent. (Complete only if address is different from mailing address in Section I.)	
DMR Mailing Name:	
DMR Mailing Street:	
DMR Mailing City, State, Zip Code:	
DMR Official Telephone Number:	


**VII. APPLICATION FILING FEE**

KPDES regulations require that a permit applicant pay an application filing fee equal to twenty percent of the permit base fee. Please examine the base and filing fees listed below and in the Form 1 instructions and enclose a check payable to "Kentucky State Treasurer" for the appropriate amount. Descriptions of the base fee amounts are given in the "General Instructions."

Facility Fee Category:	Filing Fee Enclosed:
Surface Mining Operation	\$240.00

**VIII. CERTIFICATION**

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

NAME AND OFFICIAL TITLE (type or print):	TELEPHONE NUMBER (area code and number):
John Cline / Agent	(606) 353-7201
SIGNATURE	DATE:
	09/03/2008