


US EPA ARCHIVE DOCUMENT

SUNRISE MOUNTAIN LANDFILL

(ATTACHMENT 5)
DIVERSION BERM LOCATIONS
AND SLOPES > 10%

March 21, 2008



Background Topo Based on:
KENNY AERIAL MAPPING, INC.
Flight Date: North Half March 24, 1999
South Half August 03, 1999
N.E. Canyon Updated
May 22, 2002
Client: Republic Services

LEGEND - EXISTING FEATURES	
	ROAD
	LEASE BOUNDARY
	WASTE LIMITS
	EXISTING UNLINED CHANNEL
	ROADWAY BERM
	CONCRETE HEADWALL
	PIPE DOWNDRAIN
	DRIVEOVER
	ROCK OR CONCRETE LINED DITCH/CHANNEL
	LANDFILL GAS HEADERS AND LATERALS
	DRAINAGE AREA BOUNDARY
E15	DRAINAGE AREA NAME

	Greater than 10% Slope
	Diversion Berm (~ 9,000 feet)
	Perimeter Berm
	Concentrated Run-On Flow Locations