

US EPA ARCHIVE DOCUMENT

<b>UNIT LOG</b>		1. Incident Name Kalamazoo River/Enbridge Oil Spill	2. Date Prepared 05/15/2012	3. Time Prepared 1600
4. Unit Name/Designators Situation Unit		5. Unit Leader (Name and Position) Melinda Luetke, Planning Section Chief		6. Operational Period 0700, 05/10/12 – 0700, 05/17/12
7. Personnel Roster Assigned				
Name		ICS Position		Home Base
Larry Rader		Situation Unit Leader		Chicago, Illinois
8. Activity Log				
Time	Major Events			
11:00	<p>Operational status:</p> <ul style="list-style-type: none"> <li>• Source area pond, sheen observed near center of pond.</li> <li>• Frac-Tank City, footprint reduction continues.</li> <li>• Frac-Tank City, new decon pad.</li> <li>• Confluence, no turbidity or sheen observed.</li> <li>• MP2.75 LDB, poling crew observed near new dock.</li> <li>• Island A, no sheen observed.</li> <li>• MP4.25, observed poling crews.</li> <li>• MP5.0, observed poling crews in river channel.</li> <li>• Poling crews just upstream from C0.4 boat launch.</li> <li>• MP5.75, observed sweeper boats at peninsulas above Ceresco Dam.</li> <li>• MP5.75 RDB sheen observed near sweeper boats.</li> <li>• Ceresco Dam control point, no sheen observed.</li> <li>• Ceresco Dam legacy work continued.</li> <li>• MP10.75 sediment trap location, sheen observed between sediment trap and containment boom.</li> <li>• MP10.75 sheen at sediment trap location.</li> <li>• MP11.0, RI crews observed along LDB.</li> <li>• Mill Ponds, no sheen observed.</li> <li>• MP30.8, no sheen observed within newly installed boom.</li> <li>• MP33.0, kayakers observed on river.</li> <li>• Morrow Lake Delta, no sheen observed.</li> <li>• Sweeper boat on Morrow Lake Delta near Control Point E4.</li> <li>• Control Point E4, no sheen observed.</li> <li>• Poling crew on Morrow Lake along northern shore.</li> <li>• Morrow Lake Dam, no sheen observed.</li> <li>• Poling crew observed in southwestern corner of Morrow Lake.</li> <li>• Poling crews moved to backwater channel near MP4.0 RDB.</li> </ul>			
	Additional observations: None			
13:00	Return to ICP.			
9. Prepared by (Name and Position) Larry Rader, Situation Unit Leader, USEPA-START				