

US EPA ARCHIVE DOCUMENT

<b>UNIT LOG</b>		1. Incident Name Kalamazoo River/Enbridge Oil Spill	2. Date Prepared 07/06/2012	3. Time Prepared 1700
4. Unit Name/Designators Situation Unit		5. Unit Leader (Name and Position) Melinda Luetke, Planning Section Chief		6. Operational Period 0700, 06/28/12 – 0700, 07/12/12
7. Personnel Roster Assigned				
Name		ICS Position		Home Base
Larry Rader		Situation Unit Leader		Chicago, Illinois
8. Activity Log				
Time	Major Events			
11:00	<p>Operational status:</p> <ul style="list-style-type: none"> <li>• Source area pond: sheen observed.</li> <li>• Frac-City: observed boom staged outside the decon pad.</li> <li>• Former Talmadge Creek dewatering pad location: Observed truck unloading topsoil at this location.</li> <li>• Confluence: no sheen observed.</li> <li>• Observed fishermen in river just downstream from Saylor’s Landing.</li> <li>• South peninsula above Ceresco Dam: observed sheen on upstream and downstream sides of peninsula. Sheen sweep boats were notified.</li> <li>• Sheen observed above Ceresco Dam. Sweep boat was observed operating in the area.</li> <li>• Ceresco Dam: sheen observed in southwest corner above dam and in river channel. Sheen sweep boats were present.</li> <li>• MP 5.25 LDB: sheen observed along southern shoreline above Ceresco Dam.</li> <li>• Ceresco Dam: sheen observed along the LDB along the southern wall of the dam.</li> <li>• MP 10.75 sediment trap: No sheen observed.</li> <li>• South end of Mill Pond: no sheen or activity observed.</li> <li>• Battle Creek spillway: no sheen observed.</li> <li>• MP 19.25 sediment trap, no sheen observed.</li> <li>• Morrow Lake Delta: current configuration of E4 Boom System.</li> <li>• Sweeper boat operating in northern cove on Morrow Lake.</li> <li>• Morrow Lake: sheen observed along southern shore south of fan. Sweeper boats were notified.</li> <li>• Morrow Lake Delta: poling crew in southern end of delta.</li> <li>• Morrow Lake Delta: containment boom staged for installation.</li> </ul>			
	Additional observations: None			
13:00	Return to ICP.			
9. Prepared by (Name and Position) Larry Rader, Situation Unit Leader, USEPA-START				