

US EPA ARCHIVE DOCUMENT

UNIT LOG		1. Incident Name Kalamazoo River/Enbridge Oil Spill	2. Date Prepared 09/21/2012	3. Time Prepared 1900
4. Unit Name/Designators Situation Unit		5. Unit Leader (Name and Position) Mindy Luetke, Planning Section Chief		6. Operational Period 0700, 09/20/12 – 0700, 09/27/12
7. Personnel Roster Assigned				
Name		ICS Position		Home Base
Matthew Haak		Situation Unit Leader		Houston, TX
8. Activity Log				
Time	Major Events			
0900	<p>Boat safety briefing at C0.4 boat launch.</p> <p>Operational status:</p> <ul style="list-style-type: none"> • MP5.40 LDB sheen and tar globs were observed. • MP5.45 LDB observed sheen and tar globs • MP5.55 LDB observed sheen and tar globs. • MP5.63 LDB area where sheen and tar globs were observed. • MP5.63 LDB observed sheen and tar globs. • Ceresco Dam control point boom observed a crew performing debris removal. • MP5.75 observed sheen and tar globs collecting along the control point boom. • MP5.65 RDB area where sheen and tar globs were observed. • MP5.65 RDB observed sheen and tar globs. • MP5.55 RDB sheen and tar globs were observed. • MP5.0 – C0.4 boat launch area where sheen was observed. • MP5.15 RDB sheen and tar globs observed. • MP4.5 center channel observed ribbons of sheen. • Observed the sweep boat operating between MP21.5 – 30.8. • MP26.25 sediment trap, no sheen observed. • Morrow Lake Delta poling crew observed on Gate F. • Morrow Lake Delta observed a poling crew operating along Gate C. • Morrow Lake Delta sheen observed collecting along Gate C. • Morrow Lake Delta observed a poling crew operating along Gate B. • Observed sheen collecting along Gate B. 			

	<ul style="list-style-type: none">· MP36.5 RDB sheen and tar globs observed.· Morrow Lake sheen and tar globs observed between Rowe Island and the north shore.· Observed the source area excavation.· Observed the swale restored at the source area.
1630	Complete ground survey at E4 boat launch, return to ICP.
9. Planning Functions	
<ul style="list-style-type: none">· Assisted with presentation updates.	
10. Prepared by (Name and Position)	
Matthew Haak, Situation Unit Leader, USEPA-START	