

US EPA ARCHIVE DOCUMENT



# Situation Update

October 31, 2012

# Submerged Oil

## Morrow Lake Monitoring

Poling conducted  
Monday, October 29,  
2012.

Lake activities shut  
down Tuesday, October  
30, 2012 due to high  
wind conditions.



10.29.2012 Morrow Lake Fan Delineation Poling

# Emerging Oil Management

Ceresco - Control Point  
10.29.2012

Sheen & tar Globules at Control Point



• Marshall Source



# Emerging Oil Management

Ceresco

10.25.2012

Sheen & tar Globules at Control Point



# Emerging Oil Management

Ceresco  
10.27.2012  
Boat-generated Sheen





# Emerging Oil Management

Morrow Lake South Cove

10.27.2012

Spontaneous Sheen




# Kalamazoo River

## RI Status



### Kalamazoo River RI (MDEQ)

- RI core collection ongoing per approved work plans



10.25.2012 RI Work near MP 8.5 LDB

# Source Area

Overflight on Friday,  
October 26, 2012



Sheen observed at Source Area during overflight on Friday, October 26, 2012.

Field crews did not observe sheen at this location during follow up ground inspection.



# MP 19.25 Sediment Trap

Overflight on Friday,  
October 26, 2012



Sheen observed within the sediment trap at MP 19.25 during overflight on Friday, October 26, 2012.

