

US EPA ARCHIVE DOCUMENT

DECONTAMINATION/STAGING SITE ASSESSMENT

Facility Name :	Biloxi Decon Area (Yates Construction)	Facility Location ID:	BD01
Assessment Date :	8/16/2010	Incident Name :	BP Spill
Physical Location :	215 Michael Industrial Blvd		
City, State :	Biloxi , MS	County :	Harrison

ASSESSMENT INFORMATION

General Site Information and Observations	
1. All waste stored in lined rolloff boxes?	<input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> N/A
2. Rolloff boxes covered after filled (or end of day)?	<input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> N/A
3. Any evidence of oily waste or oily waste waters?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> N/A
4. If yes, was it adequately addressed?	<input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> N/A
5. How many samples were collected?	0

Additional Comments :

Met with Jason McNeil (Yates). Only hard boom contaminated with algae is currently being decontaminated. No incident derived oily waste was present at the decon area during the visit. No samples were collected. No concerns regarding waste management practices were noted during the visit.

US EPA ARCHIVE DOCUMENT