

US EPA ARCHIVE DOCUMENT

## DECONTAMINATION/STAGING SITE ASSESSMENT

<b>Facility Name :</b>	Biloxi Decon Area	<b>Facility Location ID:</b>	BX01
<b>Assessment Date :</b>	8/10/2010	<b>Incident Name :</b>	BP Spill
<b>Physical Location :</b>	164 8th Street		
<b>City, State :</b>	Biloxi, MS	<b>County :</b>	Harrison

### ASSESSMENT INFORMATION

General Site Information and Observations	
1. All waste stored in lined rolloff boxes?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> N/A
2. Rolloff boxes covered after filled (or end of day)?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> N/A
3. Any evidence of oily waste or oily waste waters?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> N/A
4. If yes, was it adequately addressed?	<input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> N/A
5. How many samples were collected?	0
<b>Additional Comments :</b>	
<p>The facility is in operation. Mr. Cox stated that the facility has a 24 hour cycle of offloading, cleaning and reloading oom material in the containers. One empty container was located on site was labeled "oily contaminated waste. Roll off was covered, lined and no spills were noted. No other concerns regarding waste management practices were noted during the visit.</p>	

US EPA ARCHIVE DOCUMENT