

US EPA ARCHIVE DOCUMENT

DECONTAMINATION/STAGING SITE ASSESSMENT

Facility Name :	Biloxi Decon Area	Facility Location ID:	BX01
Assessment Date :	8/23/2010	Incident Name :	BP Spill
Physical Location :	164 8th Street		
City, State :	Biloxi, MS	County :	Harrison

ASSESSMENT INFORMATION

General Site Information and Observations	
1. All waste stored in lined rolloff boxes?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> N/A
2. Rolloff boxes covered after filled (or end of day)?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> N/A
3. Any evidence of oily waste or oily waste waters?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> N/A
4. If yes, was it adequately addressed?	<input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> N/A
5. How many samples were collected?	2
Additional Comments :	
EPA and CTEH collected a liquid sample from the sump that receives the rinsate from the first stage of the decontamination line. In addition, EPA and CTEH collected a sample from one roll-off container labeled as containing oil contaminated debris. The Solid Sample consisted of oil contaminated boom. Both samples collected to perform a waste characterization. No issues were observed during the site visit.	

US EPA ARCHIVE DOCUMENT