

US EPA ARCHIVE DOCUMENT

## DECONTAMINATION/STAGING SITE ASSESSMENT

<b>Facility Name :</b>	Cocodrie	<b>Facility Location ID:</b>	CocW01
<b>Assessment Date :</b>	8/1/2010	<b>Incident Name :</b>	BP Spill
<b>Physical Location :</b>	Cocodrie Marina 106 Pier 56		
<b>City, State :</b>	Chauvin, LA	<b>County :</b>	Terrebone

### ASSESSMENT INFORMATION

General Site Information and Observations	
1. All waste stored in lined rolloff boxes?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> N/A
2. Rolloff boxes covered after filled (or end of day)?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> N/A
3. Any evidence of oily waste or oily waste waters?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> N/A
4. If yes, was it adequately addressed?	
5. How many samples were collected?	6
<b>Additional Comments :</b>	
Collected solid waste sample and duplicate from roll-off including PPE, absorbent boom, and oily rags. Collected oily water (decon) sample and duplicate from one frac-tank including decon-water from boom decon. Collected oil sample and duplicate from one frac-tank including skimmer oil.	

US EPA ARCHIVE DOCUMENT