

US EPA ARCHIVE DOCUMENT

DECONTAMINATION/STAGING SITE ASSESSMENT

Facility Name :	Cocodrie	Facility Location ID:	CocW01
Assessment Date :	9/19/2010	Incident Name :	BP Spill
Physical Location :	Cocodrie Marina 106 Pier 56		
City, State :	Chauvin, LA	County :	Terrebone

ASSESSMENT INFORMATION

General Site Information and Observations	
1. All waste stored in lined rolloff boxes?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> N/A
2. Rolloff boxes covered after filled (or end of day)?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> N/A
3. Any evidence of oily waste or oily waste waters?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> N/A
4. If yes, was it adequately addressed?	<input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> N/A
5. How many samples were collected?	2

Additional Comments :

Waste Sampling Team arrived at the Cocodrie waste collection and staging area at 0930 and met with personnel from Heritage Environmental, the BP waste management contractor and environmental consultants from AECOM and Environmental Standards. Waste on-site at this time includes; approximately 140 bbl of water generated during the decontamination of hard boom contained in one 21,000 gallon storage tank and approximately 200 cubic yards of non-hazardous solid waste contained in ten 20 cubic yard roll off container.