

US EPA ARCHIVE DOCUMENT

DECONTAMINATION/STAGING SITE ASSESSMENT

Facility Name :	Cocodrie	Facility Location ID:	CocW01
Assessment Date :	9/27/2010	Incident Name :	BP Spill
Physical Location :	Cocodrie Marina 106 Pier 56		
City, State :	Chauvin, LA	County :	Terrebone

ASSESSMENT INFORMATION

General Site Information and Observations	
1. All waste stored in lined rolloff boxes?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> N/A
2. Rolloff boxes covered after filled (or end of day)?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> N/A
3. Any evidence of oily waste or oily waste waters?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> N/A
4. If yes, was it adequately addressed?	<input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> N/A
5. How many samples were collected?	0

Additional Comments :

WASR arrived at Cocodrie staging area at 1020 hours and met with Kenneth Phillips of Heritage. Heritage indicated that they have down sized approx. 50% of their staff due to operations; site ops consist of sand cleaning which is conducted on the beach and staged at Cocodrie for disposal and boat or barge decon. WASR walks site at 1025. During the site walk, Heritage indicated that there are (21) roll-off boxes located onsite; (10) empty, (8) filled with sand and boom, and (3) actively generating waste. Heritage also indicated that there are (3) frags onsite; (1) active and (2) will be removed from site today, they will not be replaced. While conducting the site assessment WASR noticed hazardous waste and non-hazardous waste drums weren't properly segregated. EPA Michael Carrillo informed the Heritage rep of the issue. WASR also reviewed all available MSDSs for the site. WASR departed the site for Metairie, LA at 1140

US EPA ARCHIVE DOCUMENT