

US EPA ARCHIVE DOCUMENT

## DECONTAMINATION/STAGING SITE ASSESSMENT

<b>Facility Name :</b>	Dulac Waste Staging Area	<b>Facility Location ID:</b>	DuIW01
<b>Assessment Date :</b>	8/23/2010	<b>Incident Name :</b>	BP Spill
<b>Physical Location :</b>	9202 Grand Caillou Road		
<b>City, State :</b>	Dulac , LA	<b>County :</b>	Terrebonne

### ASSESSMENT INFORMATION

General Site Information and Observations	
1. All waste stored in lined rolloff boxes?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> N/A
2. Rolloff boxes covered after filled (or end of day)?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> N/A
3. Any evidence of oily waste or oily waste waters?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> N/A
4. If yes, was it adequately addressed?	<input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> N/A
5. How many samples were collected?	0

**Additional Comments :**

WASR arrived at 1115 hours and met with BP waste disposal contractors from Heritage Environmental. Heritage indicated that the site receives full intermodal containers of oily boom/debris on barges or ships. Intermodal containers are offloaded directly from the barges/ships onto intermodal trailers, manifests are generated, and the rollofs are transported to an approved landfill for disposal. Full intermodal containers are not stored on site.

Several empty intermodal boxes are staged at the site for repair. There is one rolloff container of municipal wastes located on site. There is a containment pad with one drum labeled as gasoline/water mix (appears to be a diesel/water mix), one drum labeled as diesel soaked pads, and several 5-gallon buckets containing used oil. The containment held a small quantity of water and is scheduled to be vacuumed out in the immediate future. The containment was in good condition, with no sheen observed. WASR departed the site at 1135.