

US EPA ARCHIVE DOCUMENT

DECONTAMINATION/STAGING SITE ASSESSMENT

Facility Name :	Pecan Grove Staging Area	Facility Location ID:	GR01
Assessment Date :	9/9/2010	Incident Name :	BP Spill
Physical Location :	9685 Firetower Road		
City, State :	Pass Christian, MS	County :	Harrison

ASSESSMENT INFORMATION

General Site Information and Observations	
1. All waste stored in lined rolloff boxes?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> N/A
2. Rolloff boxes covered after filled (or end of day)?	<input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> N/A
3. Any evidence of oily waste or oily waste waters?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> N/A
4. If yes, was it adequately addressed?	
5. How many samples were collected?	
Additional Comments : Met with Mike Finley (WM) and Sheldon Pratt (WM). 8 roll offs (R/O) of oily contaminated material (OCM) were staged onsite. EPA and CTEH collected a sample of a sand/tarball mixture. No concerns regarding how the R/O are staged and managed were noted during the visit.	