

US EPA ARCHIVE DOCUMENT

## DECONTAMINATION/STAGING SITE ASSESSMENT

<b>Facility Name :</b>	Pecan Grove Staging Area	<b>Facility Location ID:</b>	GR01
<b>Assessment Date :</b>	7/17/2010	<b>Incident Name :</b>	BP Spill
<b>Physical Location :</b>	9685 Firetower Road		
<b>City, State :</b>	Pass Christian, MS	<b>County :</b>	Harrison

### ASSESSMENT INFORMATION

General Site Information and Observations	
1. All waste stored in lined rolloff boxes?	<input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> N/A
2. Rolloff boxes covered after filled (or end of day)?	<input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> N/A
3. Any evidence of oily waste or oily waste waters?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> N/A
4. If yes, was it adequately addressed?	<input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> N/A
5. How many samples were collected?	
<b>Additional Comments :</b> No incident derived oily waste was present at the staging area during the visit. No concerns regarding waste management practices were noted during the visit.	

US EPA ARCHIVE DOCUMENT