

US EPA ARCHIVE DOCUMENT

DECONTAMINATION/STAGING SITE ASSESSMENT

Facility Name :	Hopedale Waste Staging	Facility Location ID:	HopW01
Assessment Date :	8/10/2010	Incident Name :	BP Spill
Physical Location :	7222 Hopedale Hwy.		
City, State :	Hopedale, LA	County :	St. Bernard

ASSESSMENT INFORMATION

General Site Information and Observations	
1. All waste stored in lined rolloff boxes?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> N/A
2. Rolloff boxes covered after filled (or end of day)?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> N/A
3. Any evidence of oily waste or oily waste waters?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> N/A
4. If yes, was it adequately addressed?	<input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> N/A
5. How many samples were collected?	

Additional Comments :

A brief site walk was conducted identifying sampling locations: rolloff RB20040 containing solid wastes and frac tank #260734 containing decon wastes, and the locations for the sample staging areas. At the time of the site walk, Heritage indicated there were 6 full rollofs on site containing solid wastes. Heritage also indicated that there are 5 frac tanks onsite: 3 containing liquid decon wastes, 1 on active standby, and one in reserve.

Heritage had relocated rolloff RB20040 for sampling. During the inspection, it was noted that the liner was pulled down in one corner. Sample HopW01-100809-WS-001-1 was collected from this rolloff.

Two frac tanks were located within containment systems. The containments contained small amounts of aqueous liquids, and no sheen or adjacent stained soils were identified. Sample HopW01-100809-WL-001-1 was collected from frac tank 260743. The covers of both frac tanks at this location were open, and appeared to have been left that way for some time.

US EPA ARCHIVE DOCUMENT