

US EPA ARCHIVE DOCUMENT

## DECONTAMINATION/STAGING SITE ASSESSMENT

<b>Facility Name :</b>	Pascagoula Staging Area	<b>Facility Location ID:</b>	PG01
<b>Assessment Date :</b>	9/9/2010	<b>Incident Name :</b>	BP Spill
<b>Physical Location :</b>	2210 Petit Bois Street		
<b>City, State :</b>	Pascagoula, MS	<b>County :</b>	Jackson

### ASSESSMENT INFORMATION

General Site Information and Observations	
1. All waste stored in lined rolloff boxes?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> N/A
2. Rolloff boxes covered after filled (or end of day)?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> N/A
3. Any evidence of oily waste or oily waste waters?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> N/A
4. If yes, was it adequately addressed?	
5. How many samples were collected?	
<b>Additional Comments :</b> This area is referred to as "the Bait Shop". Met with Eric Baccigalopi (B&B Fire & Safety). Two R/O labeled "Oily Contaminated Material" (OCM) were onsite: one with PPE and one with oily boom, snare and debris. EPA and CTEH collected a sample of a sand/tar ball mixture from roll off number RB-0625235. No concerns regarding waste management practices were noted during this visit.	

US EPA ARCHIVE DOCUMENT