

US EPA ARCHIVE DOCUMENT

DECONTAMINATION/STAGING SITE ASSESSMENT

Facility Name :	Pascagoula Staging Area	Facility Location ID:	PG01
Assessment Date :	8/10/2010	Incident Name :	BP Spill
Physical Location :	2210 Petit Bois Street		
City, State :	Pascagoula, MS	County :	Jackson

ASSESSMENT INFORMATION

General Site Information and Observations	
1. All waste stored in lined rolloff boxes?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> N/A
2. Rolloff boxes covered after filled (or end of day)?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> N/A
3. Any evidence of oily waste or oily waste waters?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> N/A
4. If yes, was it adequately addressed?	<input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> N/A
5. How many samples were collected?	0
Additional Comments : Five (5) roll offs labeled oil contaminated material" located onsite. Containers filled primarily with absorbent boom and pad material. All containers were lined and covered with no spillage. No others concerns regarding waste management practices regarding the storage containers were noted during the visit.	

US EPA ARCHIVE DOCUMENT