

US EPA ARCHIVE DOCUMENT

DECONTAMINATION/STAGING SITE ASSESSMENT

Facility Name :	Port Saint Joe Decon Area	Facility Location ID:	Port Saint Joe Decon Area
Assessment Date :	9/1/2010	Incident Name :	BP Spill
Physical Location :	Industrial Road		
City, State :	Port Saint Joe , FL	County :	Gulf

ASSESSMENT INFORMATION

General Site Information and Observations	
1. All waste stored in lined rolloff boxes?	<input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> N/A
2. Rolloff boxes covered after filled (or end of day)?	<input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> N/A
3. Any evidence of oily waste or oily waste waters?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> N/A
4. If yes, was it adequately addressed?	<input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> N/A
5. How many samples were collected?	0

Additional Comments :

Operations began at this decon area on 8/5/10. Operations ended on 8/31/10. Demob/deconstruction began on 9/1/10. Approximately 500,000 feet of algae boom was decontaminated at this site during its operation. No oily boom or vessels were processed at the site. Demob/deconstruction expected to be complete by 9/8/10. A BP contractor will conduct a Phase II environmental site assessment at the site before returning the site to BP real estate operations for disposition. All residual wash water will be transported to LES in Theodore, AL, for treatment/disposal. No concerns regarding waste management practices were noted during the visit.