

US EPA ARCHIVE DOCUMENT

DECONTAMINATION/STAGING SITE ASSESSMENT

Facility Name :	Middle River (Slidell)	Facility Location ID:	SliW01
Assessment Date :	9/21/2010	Incident Name :	BP Spill
Physical Location :	Highway 90		
City, State :	Slidell , LA	County :	St. Tammany

ASSESSMENT INFORMATION

General Site Information and Observations	
1. All waste stored in lined rolloff boxes?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> N/A
2. Rolloff boxes covered after filled (or end of day)?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> N/A
3. Any evidence of oily waste or oily waste waters?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> N/A
4. If yes, was it adequately addressed?	<input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> N/A
5. How many samples were collected?	0

Additional Comments :

WASR arrived at the Middle River Location at 1130hrs; heritage reps were at lunch. WASR conducted the site assessment with Heritage site coordinator Keith Tinsley at 1300hrs. The site site activities consist of decontaminating hard boom, boats and equipment. At the time of the assessment SliW01-Middle River had 3-25 cubic yard container in use for oily debris, 1-25 cubic yard container in use for municipal waste, 1-25 cubic yard container awaiting analytical results. The site also has 3-25,000 gallon storage tanks used to hold recovered decon-water, non-potable water, and a spare. WASR observed that the roll-off boxes didn't have anything to contain or detect a leak (usually consists of plastic liner and absorbent boom); Heritage Keith Tinsley was informed of the issue. WASR departs facility at 1340.