

US EPA ARCHIVE DOCUMENT

DECONTAMINATION/STAGING SITE ASSESSMENT

Facility Name :	Middle River (Slidell)	Facility Location ID:	SliW01
Assessment Date :	7/27/2010	Incident Name :	BP Spill
Physical Location :	Highway 90		
City, State :	Slidell , LA	County :	St. Tammany

ASSESSMENT INFORMATION

General Site Information and Observations	
1. All waste stored in lined rolloff boxes?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> N/A
2. Rolloff boxes covered after filled (or end of day)?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> N/A
3. Any evidence of oily waste or oily waste waters?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> N/A
4. If yes, was it adequately addressed?	
5. How many samples were collected?	
Additional Comments : New coordinates: N 30.23736, W 089.62215 36 roll offs and 3 frac-tanks (1 non-potable, 1 backup, 1 decon-water). Observe decon activities on oily hard boom. Observe damaged boom loaded in lined and labeled roll-off. Observe all roll-offs are lined. Site is separated into three zones. One roll-off has water on the cover.	

US EPA ARCHIVE DOCUMENT