

US EPA ARCHIVE DOCUMENT

## LANDFILL SITE ASSESSMENT

<b>Facility Name :</b>	Clearview Waste Management Landfill	<b>Facility Location ID :</b>	110002225976
<b>Assessment Date :</b>	9/18/2010	<b>Incident Name :</b>	BP Spill
<b>Physical Location :</b>	2253 Mudline Road		
<b>City, State :</b>	Lake , MS	<b>County :</b>	Scott

### ASSESSMENT INFORMATION

General Site Information and Observations	
1. Is the facility currently receiving debris from BP?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> N/A
2. If no, has the facility received debris from BP in the past?	<input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> N/A
3. Which companies are transporting the BP waste?	Waste Management
4. How many BP waste loads have been rejected?	None
5. If so, why?	<input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> N/A
<b>Additional Comments :</b>	
During this operational period Parvez Mallick (EPA) conducted a telephone site assessment with Jim Johnston, the landfill operator of the Clearview Landfill, Lake, Scott County, Mississippi. Four oily contaminated loads arrived today (2 loads from Pecan Grove SA and 2 loads from Pascagoula SA).	

US EPA ARCHIVE DOCUMENT