

US EPA ARCHIVE DOCUMENT

LANDFILL SITE ASSESSMENT

Facility Name :	Clearview Waste Management Landfill	Facility Location ID :	110002225976
Assessment Date :	8/20/2010	Incident Name :	BP Spill
Physical Location :	2253 Mudline Road		
City, State :	Lake , MS	County :	Scott

ASSESSMENT INFORMATION

General Site Information and Observations	
1. Is the facility currently receiving debris from BP?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> N/A
2. If no, has the facility received debris from BP in the past?	<input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> N/A
3. Which companies are transporting the BP waste?	Waste Management, CEI Environmental Services
4. How many BP waste loads have been rejected?	None
5. If so, why?	<input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> N/A
Additional Comments :	
<p>During this operational period Javier Garcia EPA R4 departed for the Clearview Landfill to perform a coordinated assessment with MDEQ representative Jason Bridges. The team arrived at Clearview landfill at 1200 hours and met with John Pogue (Landfill lead operator). During the site visit, the team observed the off loading of two waste loads and reviewed some randomly selected manifests. Clearview is receiving waste fro the areas that were supposed to send oily wastes to the Pecan Grove Landfill. No concerns were observed during the visist.</p>	