

US EPA ARCHIVE DOCUMENT

LANDFILL SITE ASSESSMENT

Facility Name :	Magnolia Landfill	Facility Location ID :	110010380346
Assessment Date :	8/18/2010	Incident Name :	BP Spill
Physical Location :	15140 County Road 49		
City, State :	Summerdale , AL	County :	Baldwin

ASSESSMENT INFORMATION

General Site Information and Observations	
1. Is the facility currently receiving debris from BP?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> N/A
2. If no, has the facility received debris from BP in the past?	<input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> N/A
3. Which companies are transporting the BP waste?	Waste Management, Allied
4. How many BP waste loads have been rejected?	None
5. If so, why?	<input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> N/A
Additional Comments :	
<p>During this operational period John E. Johnston, Waste Monitoring Group Supervisor, departed for the Magnolia Landfill, Summerdale, Baldwin County, AL at 0930 hours for a coordinated EPA and ADEM assessment of the waste accepted at the facility. The Waste Monitoring Group Supervisor arrived at the landfill at 1015 and met with Stephanie Hopper from the ADEM. Ed Fox (Baldwin County) and Terri Graham (Baldwin County) were present during the Waste Monitoring Group and the ADEM assessment at the Magnolia Landfill.</p>	