US EPA ARCHIVE DOCUMENT

Weekly Progress Summary

Delmont, PA

Photos

Text

Carbondale, Illinois

SES Job No.

E-717

© Copyright 2006, Sevenson Environmental Services, Inc.
All rights reserved

Distribution:

Mike Slenska
Mark Gravelding
Mason Wheeler
Les Halliday
Ben Huggins
Carolyn Bury

Weekly Project Summary No.

63

Work Performed Dates:

July 10 - 16, 2006

Photo 1

REMOVING HARDWARE FROM THE WEST SIDE OF THE MOD-U-TANK

Photo 2

EXCAVATING AND DEWATERING THE BY-PASS ON GLADE CREEK

Photo 3

FINAL GRADING ALONG THE EAST SIDE OF THE SWALE

Photo 4

HEAVY RAIN / DOWNPOUR
WEDNESDAY, JULY 12TH
9:00 AM

Photo 5

CENTER OF BOTH WETLANDS

Photo 6

PUMPING WATER NEAR THE LOW POINT OF THE FORMER PROCESS AREA SURFACE COVER

Text

General Comments:

THIS WEEKS SUMMARY OF WORK ACTIVITIES INCLUDE:

GLADE CREEK CHANNEL BY-PASS

* **CONTINUING EXCAVATION OF CHANNEL REROUTE**
* **CONTINUING BACKFILL OF ORIGINAL CHANNEL**

CAMU

* **CONTINUING TO STOCKPILE SOIL FOR CAMU COVER**

MISCELLANEOUS

* **SEVERAL RAIN EVENTS DURING THE WEEK DELAYED WORK ACTIVITIES**
* **CONTINUING TO EXAMINE AND MAINTAIN EROSION AND SEDIMENTATION CONTROLS**
* **CONTINUING TO DO DAILY PERIMETER AND WORK SITE AIR MONITORING TO INSURE NO ACTION LEVELS ARE EXCEEDED**